



GREENLIGHT
ENVIRONMENTAL SERVICES

Division 5 Asbestos Register

Re-Inspection Regulatory Compliance for Workplaces



99 Thistlethwaite Street
SOUTH MELBOURNE, VIC 3205

Report No : 1340.02.ARI Rev 0
Client : GMCCA Pty Ltd ATF Chan 2015 Family Trust
Surveyed : 27 November 2024
Issued : 20 December 2024



Greenlight Environmental Services Pty Ltd



ABN: 88 497 145 734
Office 24, 15 Cochrane Rd
MOORABBIN VIC 3189

1300 888 001

www.greenlightservices.com.au



Document Control

Rev	Issued	Document Ref	Investigator	Reviewer
0	20 Dec 2024	1340.02.ARI Rev 0	Laura McKay BSc (Hons)  Senior Environmental Consultant	Michael Tierney BE  Director Licensed Asbestos Assessor (License No. LAA001018)

Site Address: 99 Thistlethwaite Street
SOUTH MELBOURNE, VIC 3205

Inspection Date: 27 November 2024

Investigator	Qualifications	Memberships
Laura McKay	<ul style="list-style-type: none">▪ Bachelor Science (Hons).▪ Work Safely at Heights.▪ Remove Non-Friable Asbestos.▪ Defensive Driving.▪ Working With Children.	<ul style="list-style-type: none">▪ Australian Institute of Occupational Hygienists (Associate).▪ Australian Institute of Health & Safety.

Report : 1340.02.ARI Rev 0 - Division 5 Asbestos Register
Site : 99 Thistlethwaite St, SOUTH MELBOURNE, VIC 3205

Issued : 20 December 2024

Expires : November 2029

Page i of iii



Table of Contents

1	Introduction	1
1.1	Previous Audits	2
2	Limitations	3
3	Site Description	5
4	Building Summary	6
5	Recommendations	7
	99 Thistlethwaite St	13
	APPENDIX B SAMPLES REGISTER	18
	B.1 Asbestos Sample Register	19
	APPENDIX C INSPECTION METHODOLOGY	21
	C.1 Methodology	22
	C.1.1 Training	22
	C.1.2 Strategy	22
	C.1.3 Presentation	22
	C.1.4 Quality Assurance	22
	C.1.5 Data Capture	23
	C.1.6 Data Security	23
	C.1.7 Asbestos Materials Analysis	23
	C.1.8 Review	24
	C.2 Areas Not Accessed	25
	APPENDIX D ASBESTOS PRIORITY & RISK ASSESSMENT METHOD	26
	D.1 Asbestos Risk Assessment Methodology	27
	D.2 Priority Assessment	29



D.2.1	What does the Priority Assessment Mean?.....	29
D.2.2	Priority Score 0-97 - P4 or P3 - Low or Medium Risk.....	29
D.2.3	Priority (Scores 98-145) - P2 - Medium Risk.....	30
D.2.4	Priority (Scores 146-240) - P1 - High Risk.....	30
APPENDIX E	LAB REPORTS.....	31

Figures

Figure 1 - Site Address Aerial View.....	5
Figure 2 - Risk Assessment Table combined with our Algorithm.....	27
Figure 3 -Example Algorithmic Risk Assessment.....	28
Figure 4 - Priority Assessment	29

Tables

Table 1 – Previous Audit.....	2
Table 2 - Site Summary of Findings	6
Table 3 - Asbestos Labelling Required	8
Table 4 - Asbestos Sample Register - Greenlight November 2024 Audit.....	19
Table 5 - Greenlight Environmental Services march, 2019 Audit.....	19



1 Introduction

Greenlight Environmental Services Pty Ltd (Greenlight) was engaged by Garry Chan of GMCCA ATF Chan 2015 Family Trust to conduct a Division 5 Asbestos Re-Inspection Audit & Register of the site located at 99 Thistlethwaite St, SOUTH MELBOURNE, VIC 3205.

The purpose of the survey was to:

- Reinspect all previously identified asbestos items (see [Table 1 – Previous Audit](#));
- Document all previously identified non-asbestos items where those items were either sampled or assessed as similar to a sampled material;
- Conduct a site walkover review of the buildings while carrying out the above works for any items that may have been missed during previous audits, sample and document as may be required
- Perform a risk assessment of asbestos materials based on their condition, placement, surface treatment and nature, noting the extent of the materials in square metres; and
- Provide advice regarding the removal of asbestos materials identified in the survey if they are to be disturbed by any planned works, or to provide advice about their ongoing management if they are to remain in place.

The Division 5 Asbestos Register constitutes an **Asbestos Register** under the Work Safe Victoria Compliance Codes:

- [Managing Asbestos in Workplaces \(2019\)](#); and
- [Removing Asbestos in Workplaces \(2019\)](#).

These codes were developed by Work Safe Victoria as a practical guide to duty holders under the Occupational Health and Safety Regulations (2017) and the Victorian Occupational Health and Safety Act 2004.



1.1 Previous Audits

The scope of works for the November, 2024 Audit of 99 Thistlethwaite St by Greenlight, was to assess the condition of the asbestos containing materials that were previously identified in the following previous audit:

Table 1 – Previous Audit

Previous Audits	Report Title	Report Reference	Company
march, 2019	Division 5 Asbestos Register	1340.01.DV5A	Greenlight Environmental Services

Based on the report above, the condition of all noted asbestos containing materials were assessed, any additional potential asbestos containing materials identified in the walk-through assessment were noted and sampled where necessary, and any previously noted non-asbestos items that were sampled were located and all documented within this register.



2 Limitations

Greenlight Environmental Services and our staff members are trained and suitably qualified to deliver a thorough and diligent investigation and report.

Although our work is performed to a professional standard, the potential variance between the limitations of our investigation, the cost of our services all possible issues of concern, and any loss or damages which may be associated with our work are such that we cannot warrant that all asbestos materials have been identified. We therefore limit any potential liability associated with our work to the cost of our services.

If unexpected asbestos materials are identified during works, an unexpected finds protocol should be followed - i.e. stop work, isolate the area, and have investigated by an appropriately qualified consultant or occupational hygienist.

All work conducted and/or reports/information produced by Greenlight Environmental Services Pty Ltd are prepared for a specific objective and within a specified scope of work as agreed between the Client and Greenlight Environmental Services Pty Ltd. As such this document is only for the use of the Client for the intended objective and may not be suitable for any other purpose.

No parties other than the Client may use this document without first conferring with Greenlight Environmental Services Pty Ltd. Before passing this document onto a third party, the Client must inform the third party of any relevant information relating to this document. It is the responsibility of any party using this report to check to their satisfaction if this report is suitable for their intended use.

All information and/or report(s) prepared by Greenlight Environmental Services Pty Ltd should not be reproduced and/or presented/reviewed except in full.

Unless specifically mentioned, the inspection did not cover:

- Materials dumped, hidden, or otherwise placed in locations which one could not reasonably anticipate.



- Inaccessible/hidden locations, including wall cavities, under concrete slabs and lift wells.
- Materials other than standard building materials e.g. materials in special purpose facilities.
- Ground surface and underground areas.
- Mechanical, electrical, or other items/materials not directly associated with the building structure.
- Materials other than asbestos as identification of a range of other possible hazardous substances can require specialised analysis/inspection techniques.

Settled dusts are known to exist in a variety of locations in the general environment and possibly contain a range of substances which may be hazardous at varying levels, particularly if the dust is in the vicinity of hazardous materials such as asbestos containing materials or paint containing lead. Furthermore, dusts present may originate from a variety of known and unknown complex sources (such as environmental/atmospheric) that are not related to the presence of bulk hazardous building materials e.g. combustions emissions from automobiles or industry.

Due to the above mentioned potential complex sources of dust which may not be identifiable, settled dust is not sampled or commented on except where otherwise noted.



3 Site Description

The site was located at 99 Thistlethwaite St, SOUTH MELBOURNE, VIC 3205 and consisted of a single-storey warehouse predominately constructed with asbestos roof & brick walls.





Figure 1 - Site Address Aerial View



4 Building Summary

The table below provides a quick guide to the general location, extent, and friability of asbestos items on the site. A complete description of the survey findings with in-line photos and a risk assessment for each item is provided in [Appendix A - Asbestos Register](#).

Table 2 - Site Summary of Findings

Building	Building Photo	Bonded Asbestos	Friable Asbestos
99 Thistlethwaite St		Yes 1 x location 320m ²	Yes 2 x locations 320.0m ²



5 Recommendations

Please note that any planned works on the site should proceed under an '**Unexpected Finds Protocol**', whereby if potential asbestos materials are identified that are not covered within this report, works are stopped within the relevant area and the area is re-inspected prior to works re-commencing.

This document should remain on the site during any planned works for examination by workers and as proof of compliance.

Below are some general procedures that should be followed to assist in the control of asbestos materials on the site:

1. Asbestos items as listed in the register for the site [Asbestos Register \(Appendix A\)](#) should not be disturbed by activities such as drilling, grinding, water-blasting, cutting, sanding or demolition.
2. The most preferred management method for any asbestos materials is to have them removed from site by a licensed Class A or Class B asbestos removalist. Materials noted as **Friable** in the Asbestos Register may only be removed by a **Class A Licensed Asbestos Removalist**.

Benefits of removing all asbestos items include:

- Eliminating the risk of any unplanned disturbance of asbestos materials impacting the health of occupants;
- Increase in property valuation, likely to be equivalent to or greater than the cost of removal;
- Decrease in insurance premiums on the reputation benefits for companies that choose to eliminate all asbestos.

One approach that property owners take is to package the cost of asbestos removal works in with any planned refinance arrangements.



3. A clearance certificate for any asbestos removal works prepared by an independent and qualified company such as Greenlight is required under the regulations for all removals greater than 10 square metres and for *any* amount of friable asbestos materials.
4. Air monitoring is required both during and following the removal of *any* amount of friable asbestos removal under the state regulations and is strongly recommended for all other asbestos removal work, in particular where:
 - a. Works are indoors;
 - b. Children, the elderly or the infirmed usually occupy the immediate or adjacent areas
 - c. There are stakeholder concerns. These reports can assist with reassuring people that works were conducted in a safe manner.
5. The labelling of asbestos materials as well as the entrances to any buildings containing asbestos materials is mandatory for all workplaces under Victorian regulations (Greenlight can assist with labelling works on request).

Table 3 - Asbestos Labelling Required

Asbestos Items	Unlabelled	Labels Needed	Signs Needed
3	All Labelled	None Required	1

6. An Asbestos Management Plan (AMP) for any site containing asbestos is strongly recommended under the regulations. This is a separate document that outlines:
 - a. The responsibilities of parties on the site (e.g. managers, tenants or subcontractors);
 - b. Any particular asbestos issues with respect to this site;



- c. Procedures to be followed for typical 'working with asbestos' action;
- d. Emergency procedures.

Greenlight can prepare a suitable AMP for the site on request.

- 7. Work Safe Victoria Regulations further require the regular inspection of the identified asbestos materials are to be undertaken (at a minimum of every 5 years) for all workplaces.

This five-yearly audit is important as asbestos materials tend to degrade over time or may have been damaged in the intervening time. The AMP for the sites should be reviewed also every five years and in conjunction with the Asbestos Register review.

Next Audit Due: November 2029.

- 8. All contractors working on the site should be made aware of the presence of asbestos materials and their location by a site induction process. Any employees who may disturb asbestos materials as part of their ongoing works should be familiarised with all asbestos items on the site as part of their employee induction.
- 9. In some cases, the state of asbestos materials, or planned disturbance works within the area may be such that their removal is either recommended or is regarded as mandatory under the legislation. If this is the case for any materials on the site, a comment to that effect has been made against the item within the [Asbestos Register \(Appendix A\)](#).
- 10. If asbestos materials are to remain on site, they must not be disturbed by activities such as drilling grinding, sanding, or water-blasting. It should be noted that water-blasting asbestos is an illegal act and considered to be a pollution incident by the EPA. Contamination of property arising from water-blasting activities is typically not covered by insurance companies due to the illegal nature of such actions.



11. If disturbance to asbestos materials is required for some reason (for example drilling to install fittings on the material) the following are the preferred actions (in order of preference):
 - a. Remove the *entire extent* of asbestos materials to be disturbed and replace with a non-asbestos alternative prior to works (e.g. all eaves);
OR
 - b. Remove the *immediate extent* of asbestos materials to be disturbed and replace with a non-asbestos alternative prior to works (e.g. eaves panels that require drilling only); OR
 - c. Have the drilling/disturbance works conducted by a licensed Class A or Class B Asbestos removalist, OR
 - d. Have the drilling/disturbance works conducted by a suitably qualified contractor following a suitable asbestos disturbance work plan.
12. The Asbestos Register should be updated following
 - a. The removal and disposal of any asbestos materials;
 - b. Any notable changes in condition to the materials;
 - c. Refurbishment works that significantly alter the layout of a property.
13. Prior to any demolition or refurbishment works on the site, a **Division 6 Asbestos Audit** of the areas that may be affected by the proposed scope of works is to be carried out by a suitably qualified occupational hygiene company such as Greenlight.

Please note that under the Victorian regulations, this second audit is *required* as a second step and that this audit is not considered suitable for this purpose.

Such audits also additionally assess the relevant area or building for the presence of other hazardous materials such as lead in dust, lead in paint, metallic lead, SMF, PCBs and Ozone depleting substances



14. The review of this document should form a part of the Division 6 Asbestos Audit as well as a more intrusive testing of the area for asbestos.
15. Further advice and guidance on asbestos materials in the work environment may be found in the WorkSafe Victoria Compliance Codes - [Managing Asbestos in Workplaces](#); and [Removing Asbestos in Workplaces](#), 2019.
16. It is recommended that all documentation regarding asbestos removal, treatment or investigation be kept on file indefinitely. As such a suitable method of storage for such documents should be implemented.





APPENDIX A ASBESTOS REGISTER

Report : 1340.02.ARI Rev 0 - Division 5 Asbestos Register
Site : 99 Thistlethwaite St, SOUTH MELBOURNE, VIC 3205

99 Thistlethwaite St






Asbestos Extent:	640.0m²	Inspected on	27 November 2024
Asbestos Items:	3	Inspected by	Laura McKay BSc (Hons) Senior Environmental Consultant
High Risk Items:	None		




Location		Assessment Details	Risk	Photo	Controls
99 Thistlethwaite St - Exterior					
ASBESTOS	Roof Corrugated asbestos cement sheeting	Method Sampled in Previous Audit (1340.01/AS01) Outcome Chrysotile & Amosite Asbestos Detected Condition Good Extent 320.0 square metres	Low Risk Priority P3		Maintain in good condition & do not disturb - e.g. do not drill, cut, grind, sand, or blast. Remove prior to any works that may disturb the materials by a Licensed Class A or Class B Asbestos Removalist. Engage a Hygienist such as Greenlight to visually inspect any removal works & issue a clearance certificate prior to normal occupancy. Air monitoring is
			Non-Friable Asbestos Class A / B License Required		
ASBESTOS	Roof Roof box gutters - may contain build-up of asbestos dust & debris	Method Visually Assessed Outcome Assumed to Contain Asbestos Condition Moderate Extent 20.0 square metres Labelled? Not Required (Height)	Medium Risk Priority P2		Run-off from asbestos roofing in degrading condition can cause contamination in the guttering. Ideally the roof should be sealed or consider removal to prevent this kind of occurrence. (Note you cannot perform paint prep on the asbestos roof) Alternatively, Gutters can be first cleaned by a Licensed Class A Asbestos removalist.
			Friable Asbestos Class A License Required		

Report : 1340.02.ARI Rev 0 - Division 5 Asbestos Register
Site : 99 Thistlethwaite St, SOUTH MELBOURNE, VIC 3205






Location		Assessment Details		Risk	Photo	Controls
99 Thistlethwaite St - Exterior (... continued)						
	Windows Metal frames - putty	Method Sampled in Previous Audit (1340.01/AS02)	Outcome No Asbestos Detected	No Asbestos Risk Identified		
	Throughout General construction (except as noted above) - brick walls & metal & plastic pipes to the rear wall	Method Visually Assessed	Outcome No Asbestos Identified	No Asbestos Risk Identified		
99 Thistlethwaite St - Interior						
	Main Warehouse Area Ceiling & boxing under gutters - timber	Method Visually Assessed	Outcome No Asbestos Identified	No Asbestos Risk Identified		




Location		Assessment Details	Risk	Photo	Controls
99 Thistlethwaite St - Interior (... continued)					
	Main Warehouse Area Windows - putty	Method Sampled in Previous Audit (1340.01/AS03) Outcome No Asbestos Detected	No Asbestos Risk Identified		
	Staffroom Negative blue seamless vinyl floor cover replaced with new black seamless vinyl with non-asbestos characteristics Comment: Sample reference 1340. 01/AS04	Method Visually Assessed Outcome No Asbestos Identified	No Asbestos Risk Identified		
	Staffroom Infill panel above & beside south-western door - cement sheeting	Method Sampled (GL012318) Outcome No Asbestos Detected	No Asbestos Risk Identified		



Location	Assessment Details	Risk	Photo	Controls
99 Thistlethwaite St - Interior (... continued)				
Toilet Negative blue seamless vinyl floor cover removed - ceramic floor tiles stuck straight onto concrete flooring <i>Comment: Reference sample 1340. 01/AS04</i>	Method Visually Assessed Outcome No Asbestos Identified	No Asbestos Risk Identified		
Toilet General construction (except as noted above) - wood fibre board ceilings, wood fibre board & brick walls, concrete flooring under floor covers	Method Visually Assessed Outcome No Asbestos Identified	No Asbestos Risk Identified		
Throughout General construction (except as noted above) - plaster board & timber ceilings, plaster board, wood fibre board & brick walls, concrete flooring under floor covers	Method Visually Assessed Outcome No Asbestos Identified	No Asbestos Risk Identified		



Location		Assessment Details	Risk	Photo	Controls
99 Thistlethwaite St - Ceiling Cavity					
ASBESTOS	Space between Asbestos Roof & Internal Ceilings	Method Visually Assessed	Medium Risk Priority P2 Friable Asbestos Class A License Required		Avoid any drilling, cutting or grinding of the ceiling material. Confirm Status & remove as soon as practicable and prior to any demolition or refurbishment works that will disturb the materials by a licensed Class A Asbestos Removalist. Engage a Hygienist such as Greenlight to visually inspect any removal works, carry out air monitoring both during & following removal & to issue a clearance certificate prior to normal occupancy.
	Build-up of asbestos dust likely present	Outcome Assumed to Contain Asbestos			
		Condition Good			
		Extent 300.0 square metres			
		Labelled? Not Required (Height)			



APPENDIX B

SAMPLES REGISTER



B.1 Asbestos Sample Register

The two tables below provide information about the sample locations of any asbestos samples taken through the history of auditing at the site as has been provided to or carried out by Greenlight.

This information is intended to complement the findings within the NATA endorsed sample reports. Samples taken from any demolished or sold buildings or areas that have undergone asbestos removal may have been omitted from this summary list.

Current Audit – Asbestos Samples

Table 4 - Asbestos Sample Register - Greenlight November 2024 Audit

Sample Number	Sample Location	Outcome
Lab Report Reference: 1165039-AID.pdf		
GL012318	99 Thistlethwaite St - Interior - Staffroom - Infill panel above & beside south-western door - cement sheeting	No Asbestos Detected

Previous Audits – Asbestos Samples

Table 5 - Greenlight Environmental Services march, 2019 Audit

Sample Number	Sample Location	Outcome
Lab Report Reference: LRM Global Report: 38132.000		
1340.01/AS01	Exterior - roof - corrugated asbestos cement sheeting	Chrysotile & Amosite Asbestos Detected
1340.01/AS02	Exterior - windows throughout - putty	No Asbestos Detected

Report : 1340.02.ARI Rev 0 - Division 5 Asbestos Register
Site : 99 Thistlethwaite St, SOUTH MELBOURNE, VIC 3205



Sample Number	Sample Location	Outcome
1340.01/AS03	Interior - main warehouse area - window putty	No Asbestos Detected
1340.01/AS04	Interior - staff room - blue seamless vinyl floor cover adjacent to kitchenette	No Asbestos Detected

Please refer to [APPENDIX E](#) on **page 31** for the NATA endorsed Asbestos Sample Analysis Report/s.



APPENDIX C INSPECTION METHODOLOGY



C.1 Methodology

C.1.1 Training

Greenlight follows an in-house training regime of all consultants based on methodologies recommended by the British Occupational Hygiene Society as well as in-house methods and principals that are unique to Greenlight and considered to be world's best practice.

All consultants are tertiary qualified in either Science, Engineering or Occupational Hygiene and are run through a robust training regime with ongoing mentorship from senior consultants and professional development opportunities.

C.1.2 Strategy

Our signature approach is called the '**Elimination Method**' in which a structure is broken down into areas which are subjected to an analysis based on the consultants experience and training documenting all hazardous elements systematically until the consultant achieves an 'inert base'. This final base in each area is also documented.

C.1.3 Presentation

Each of our entries is presented with a photograph in-line with the entry and utilising colour coding. Our reports aim to be clear, thorough and well presented. Our consultants are encouraged to speak clearly and concisely and to avoid being overly wordy.

This approach is intended to be in line with our overall branding and company strategy which aims to communicate as clearly as possible and provide **clear signalling** to our clients. This is to avoid any possible misunderstanding of risks.

C.1.4 Quality Assurance

Sample information is parsed from the NATA accredited laboratory directly into our software via a robust data quality check which automatically flags any discrepancies between lab and field data. For example:

Report : 1340.02.ARI Rev 0 - Division 5 Asbestos Register
Site : 99 Thistlethwaite St, SOUTH MELBOURNE, VIC 3205



- The total number of samples must exactly match
- The Booking ID for the job must exactly match
- The sample numbers within each set must exactly match
- All lab results must be in a recognised format.

If any of these criteria is not passed, then the report is not generated, and the matter is flagged to our reporting team using API integration with our CRM and reporting system.

C.1.5 Data Capture

We use digital data entry on-site with the use of a tablet device and **custom-made software** which has a number of unique data quality assurance methods which have been custom built for the hazardous materials identification industry.

All data is parsed into a document in combination with the lab data without any room for human transposition error.

This process ensures both speed, timeliness and a high degree of accuracy with very limited potential for sources of human error.

C.1.6 Data Security

All data is stored securely on cloud-based servers and backed up into separate systems. Access to data is limited to a small number of senior staff who are trained in data security and can only access data via 2FA devices.

C.1.7 Asbestos Materials Analysis

All accessible areas of the site are thoroughly inspected for the determination of the type, condition and extent of asbestos building materials that may be present.

Where visual examination of a material proves to be inconclusive, samples are collected for laboratory analysis. Samples are collected by non-destructive and non-intrusive techniques wherever possible.



Determination of materials containing or potentially containing asbestos materials is based on a visual examination and/or sampling and analysis.

All asbestos samples are analysed by an independent NATA accredited Laboratory. Asbestos samples are analysed for the qualitative identification of asbestos type fibres in bulk using Polarised Light Microscopy and Dispersion Staining Techniques.

C.1.8 Review

All reports are peer reviewed by another consultant. In cases where:

- High risk or Priority 1 items are encountered; or
- A particular situation is flagged as unusual by the investigating consultant;

The report is reviewed by a Senior consultant.



C.2 Areas Not Accessed

All reasonable effort is made to investigate the entire property. Where this is not possible due to restrictions caused by construction or safety, an entry is made within the register noting that the area was not inspected and the reason.

Such areas may include, for example:

- Height restricted areas;
 - Gas, electrical, chemical, or pressurised service lines;
 - Within service shafts, ducts, and wall cavities;
 - Areas obstructed by installed equipment; and
- Locked areas to which no key is available at the time of inspection.

Further investigation of these areas should be carried out as soon as practicable and prior to refurbishment or demolition activities that may disturb the areas.

Where an area is locked, the consultant is required to notify the relevant client contact and to give them reasonable opportunity to rectify the situation. These areas are also documented in the register.



APPENDIX D ASBESTOS PRIORITY & RISK ASSESSMENT METHOD

D.1 Asbestos Risk Assessment Methodology

For a thorough, consistent, and transparent assessment of asbestos risk, Greenlight employs a 14-Point approach which is an adaptation of the UK Health & Safety Executive recommended algorithmic risk assessment methodology, combined with the traditional risk matrix methodology as is commonly used in Australia.

For any item where asbestos is identified, the consultant selects options relating to the item's material nature, surface treatment, placement and environment which is scored by Greenlights custom made software. The outcome of this process yields an overall risk for the item in easy-to-understand terms - **High, Medium, or Low**.

Likelihood Factors:

1. Condition
2. Labelling
3. Extent
4. Accessibility
5. Fixed vs loose material
6. Frequency of use of area
7. Specific Location

Consequence Factors:

8. Friable vs non-friable material
9. Material type risk
10. Surface Treatment
11. General Location
12. Occupancy
13. Presence of sensitive receptors
14. Asbestos Type

TOTAL ___/120

TOTAL ___/120




Figure 2 - Risk Assessment Table combined with our Algorithm



Likelihood				
Condition	Good 0	Minor Damage 5	Moderate 10	Poor 40
Labelling	Labelled 1	Unlabelled 10		
Extent (m2)	<1 0	<10 5	<100 10	100 or greater 25
Accessibility	Restricted 5	Easily Accessed 10		
Fixed or Loose	Fixed 0	Loose 10		
Frequency of Use of Area	Weekly 0	Daily - Low Use 5	Daily - High Use 10	
Location - Exterior	At height 0	Ground level 10		

Consequence				
Material Type Risk	Low 0	High 20		
Surface Treatment	Encapsulated 0	Painted 5	Encapsulation Damaged 10	Unsealed 20
General Location	Exterior 5	Interior / Confined 10		
Occupancy	1-3 5	4-10 10	>10 20	
Sensitive Receptors	Not Present 0	Present 10		
Friability	Non-Friable (Bonded) 5	Friable 20		
Asbestos Type	Chrysotile 5	Amosite 10	Crocidolite 20	Pending 5

	Consequence	Likelihood
Asbestos Eaves	35	30

Consequence					
Likelihood		Minor			
Unlikely		Low			

Figure 3 -Example Algorithmic Risk Assessment



D.2 Priority Assessment

It can be helpful to assign a priority to each item - Priorities P1 to P4. The priority assessment is based on the overall score for all 14 items accounted for in the Risk Assessment (i.e. the consequence score added to the likelihood score).

D.2.1 What does the Priority Assessment Mean?




Figure 4 - Priority Assessment

The priority score gives a good indication of the 'health' of the asbestos item and is an excellent guide as to where further actions are needed.

D.2.2 Priority Score 0-97 - P4 or P3 - Low or Medium Risk

Many of your asbestos items for the site are likely in this category. These lower risk items are generally in good condition and while left undisturbed (by actions such as drilling, grinding, or sanding), will pose a negligible risk to occupants of the area.



It should be noted however that low risk items become high risk if they are mechanically disturbed by actions such as drilling, grinding, sanding, or water-blasting. It is for this reason that we always recommend asbestos items be removed wherever practicable.

D.2.3 Priority (Scores 98-145) - P2 - Medium Risk

Items with a Priority Score between 98 and 145 are a medium risk and may require some treatment if they are to remain on site. For example, it may relate to bonded asbestos materials in a poor condition or moderately damaged. It may also relate to some friable asbestos materials with some damage to the materials encapsulation.

Ideally (as with all asbestos items) these materials should be removed from the site.

D.2.4 Priority (Scores 146-240) - P1 - High Risk

Asbestos items with a Priority Score between 146 and 240 are usually friable in nature and will require some immediate actions to be taken. It may be necessary to isolate the area and have remediation works carried out as a priority. Restrict access to areas with these items and erect signage at the entrances until works can be carried out.



APPENDIX E LAB REPORTS

Report : 1340.02.ARI Rev 0 - Division 5 Asbestos Register
Site : 99 Thistlethwaite St, SOUTH MELBOURNE, VIC 3205

Issued : 20 December 2024

Expires : November 2029

Page **31** of **31**



LRM Global Pty Ltd
65 Stubbs Street
Kensington VIC 3031

Fax: (03) 9371 3499
Email: enquiries@lrmglobal.com.au
Web: www.lrmglobal.com.au
Telephone: (03) 9371 3400
ABN: 34 116 540 277

Qualitative Identification of Asbestos in Bulk Samples

Greenlight Environmental Services
Level 9, Suite 1 440 Collins St
Melbourne Vic 3000

Client Ref: 99 Thistlethwaite St, South Melbourne

Job Number: 38132.000

Batch Number: -

Received Date: March 18, 2019

Analysed Date: March 21, 2019

No of Samples: 4

Dear Michael Tierney,

This report presents the analytical results of samples forwarded by Greenlight Environmental Services for asbestos analysis.

Methodology:

The samples were examined under a Stereo Microscope and selected fibres were analysed by Polarized Light Microscopy in conjunction with Dispersion Staining Method. (**LRM Global ID Method 1**) and AS4964 - 2004

Analytical Results:

Sample No.	Sample Description	Result
1340.01/AS01	The sample consisted of fibro plaster cement Location: Exterior – Roofing – Corrugated cement sheeting Sample Dimensions: 0.3cm X 0.2cm X 0.2cm	Amosite Asbestos Detected Chrysotile Asbestos Detected
1340.01/AS02	The sample consisted of mastic Location: Exterior – Windows Throughout – Window putty Sample Dimensions: 0.2cm X 0.2cm X 0.2cm	No Asbestos Detected
1340.01/AS03	The sample consisted of mastic Location: Interior – Main Warehouse Area – Window putty Sample Dimensions: 0.3cm X 0.3cm X 0.2cm	No Asbestos Detected
1340.01/AS04	The sample consisted of vinyl sheet Location: Interior – Staff Room – Blue seamless vinyl floor cover adjacent kitchenette Sample Dimensions: 5.0cm X 3.0cm X 0.3cm	No Asbestos Detected



Approved Identifier
Karu Jayasundara



Report Issued by
Karu Jayasundara



**WORLD RECOGNISED
ACCREDITATION**
Accreditation No: 15684

Accredited for compliance with ISO/IEC 17025
The results of the tests, calibrations and/or
measurements included in this document are traceable
to Australian Standards.

Greenlight Enviro Serv P/L ATF Greenlight Serv
Office 24, 15 Cochranes Rd
Moorabbin
VIC 3189

NATA Accredited
Accreditation Number 1261
Site Number 1254

Accredited for compliance with ISO/IEC 17025—Testing
NATA is a signatory to the ILAC Mutual Recognition
Arrangement for the mutual recognition of the
equivalence of testing, medical testing, calibration,
inspection, proficiency testing scheme providers and
reference materials producers reports and certificates.

Attention: - ATTN: Greenlight Lab Results
Report 1165039-AID
Project Name 99 Thistlethwaite St SOUTH MELBOURNE VIC 3205
Project ID 1340.02
Received Date Nov 27, 2024
Date Reported Nov 28, 2024

Methodology:
**Asbestos Fibre
Identification**

Conducted in accordance with the Australian Standard AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004 and in-house Method LTM-ASB-8020 by polarised light microscopy (PLM) and dispersion staining (DS) techniques.
NOTE: Positive Trace Analysis results indicate the sample contains detectable respirable fibres.

**Man-made vitreous
fibre (MMVF)**

Fibres exhibiting isotropic characteristics, including glass fibres, glass wool, rock wool, slag wool, ceramic fibres and bio-soluble fibres. *NOTE: previously known as "synthetic mineral fibre" (SMF). Simple analytical procedures such as polarised light microscopy cannot detect or reliably identify asbestos in some types of commercial products containing asbestos, either because the fibres are below the resolution of optical microscopy or because the matrix material adheres too strongly to the fibres. For these types of products, electron microscopy may be necessary.*

**Subsampling Soil
Samples**

The sample submitted is dried and passed through a 10 mm sieve followed by a 2 mm sieve. All fibrous matter greater than 10 mm and greater than 2 mm and the material passing through the 2 mm sieve are retained and analysed for the presence of asbestos. If the sub 2mm fraction is greater than approximately 30 g to 60 g, then a subsampling routine based on ISO 3082:2017(E) is employed.
NOTE: Depending on the nature and size of the soil sample, the sub-2 mm residue material may need to be subsampled for trace analysis, in accordance with AS 5370:2024.*

**Bonded asbestos-
containing material
(ACM)**

The material is first examined, and any fibres are isolated for identification by PLM and DS. Where required, interfering matrices may be removed by disintegration using a range of heat, chemical or physical treatments, possibly in combination. The resultant material is then further examined in accordance with AS 5370:2024*.
NOTE: Even after disintegration, it may be difficult to detect the presence of asbestos in some asbestos-containing bulk materials using PLM and DS. This is due to the low grade or small length or diameter of the asbestos fibres present in the material or to the fact that very fine fibres have been distributed intimately throughout the materials. Vinyl/asbestos floor tiles, some asbestos-containing sealants and mastics, asbestos-containing epoxy resins and some ore samples are examples of these types of material, which are difficult to analyse.

**Limit of Reporting
(LOR)**

The performance limitation of the AS 5370:2024* method for non-homogeneous samples is around 0.1 g/kg (equivalent to 0.01% (w/w)). Where no asbestos is found by PLM and DS, including Trace Analysis, this is considered to be at the nominal reporting limit of 0.01% (w/w). The NEPM screening level of 0.001% (w/w) is intended as an on-site determination, not a laboratory limit of reporting, per se. Examination of large sample size (e.g., 500 mL) may improve the likelihood of detecting asbestos, particularly AF, to aid assessment against the NEPM criteria. Gravimetric determinations to this level of accuracy are outside of AS 5370:2024*, and hence, NATA Accreditation does not cover the performance of this service (non-NATA results are shown with an asterisk).
NOTE: NATA News March 2014, p.7, states in relation to AS 4964-2004: "This is a qualitative method with a nominal reporting limit of 0.01 % " and that currently in Australia "there is no validated method available for the quantification of asbestos". This report is consistent with the analytical procedures and reporting recommendations in the NEPM and the WA DoH.

Project Name 99 Thistlethwaite St SOUTH MELBOURNE VIC 3205
Project ID 1340.02
Date Sampled Nov 27, 2024
Report 1165039-AID

Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
GL012318	24-No0077785	Nov 27, 2024	Approximate Sample 1g / 15 x 5 x 2mm Sample consisted of: Cement sheet	No asbestos detected. Organic fibres detected. No trace asbestos detected.

Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8020	Melbourne	Nov 27, 2024	Indefinite



web: www.eurofins.com.au
email: EnviroSales@eurofins.com

Melbourne 6 Monterey Road Dandenong South VIC 3175 +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 +61 3 8564 5000 NATA# 1261 Site# 25403	Sydney 179 Magowar Road Girraween NSW 2145 +61 2 9900 8400 NATA# 1261 Site# 18217	Canberra Unit 1,2 Dacre Street Mitchell ACT 2911 +61 2 6113 8091 NATA# 1261 Site# 25466	Brisbane 1/21 Smallwood Place Murarrie QLD 4172 T: +61 7 3902 4600 NATA# 1261 Site# 20794 & 2780	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 +61 2 4968 8448 NATA# 1261 Site# 25079	Perth 46-48 Banksia Road Welshpool WA 6106 +61 8 6253 4444 NATA# 2377 Site# 2370 & 2554	Auckland 35 O'Rorke Road Penrose, Auckland 1061 +64 9 526 4551 IANZ# 1327	Auckland (Focus) Unit C1/4 Pacific Rise, Mount Wellington, Auckland 1061 +64 9 525 0568 IANZ# 1308	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 +64 3 343 5201 IANZ# 1290	Tauranga 1277 Cameron Road, Gate Pa, Tauranga 3112 +64 9 525 0568 IANZ# 1402
---	--	--	--	---	--	--	---	--	--	--

Company Name: Greenlight Enviro Serv P/L ATF Greenlight OH&S
Address: Office 24, 15 Cochranes Rd
Moorabbin
VIC 3189

Order No.:
Report #: 1165039
Phone: 0416 388 825
Fax:

Received: Nov 27, 2024 6:35 PM
Due: Nov 28, 2024
Priority: 1 Day
Contact Name: - ATTN: Greenlight Lab Results

Project Name: 99 Thistlethwaite St SOUTH MELBOURNE VIC 3205
Project ID: 1340.02

Eurofins Analytical Services Manager : Zoe Burke

Sample Detail						Asbestos Absence / Presence
Melbourne Laboratory - NATA # 1261 Site # 1254						X
External Laboratory						
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID	
1	GL012318	Nov 27, 2024		Building Materials	M24-No0077785	X
Test Counts						1

Internal Quality Control Review and Glossary General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with the colour blue indicates data provided by customer that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to the most recent version of the 'Sample Preservation and Container Guide' for holding times (QS3001).

Units

% w/w:	Percentage weight-for-weight basis, e.g. of asbestos in asbestos-containing finds in soil samples (% w/w)
F/fld	Airborne fibre filter loading as Fibres (N) per Fields counted (n)
F/mL	Airborne fibre reported concentration as Fibres per millilitre of air drawn over the sampler membrane (C)
g, kg	Mass, e.g. of whole sample (M) or asbestos-containing find within the sample (m)
g/kg	Concentration in grams per kilogram
L, mL	Volume, e.g. of air as measured in AFM (V = r x t)
L/min	Airborne fibre sampling Flowrate as litres per minute of air drawn over the sampler membrane (r)
min	Time (t), e.g. of air sample collection period

Calculations

Airborne Fibre Concentration: $C = \left(\frac{A}{a}\right) \times \left(\frac{N}{n}\right) \times \left(\frac{1}{r}\right) \times \left(\frac{1}{t}\right) = K \times \left(\frac{N}{n}\right) \times \left(\frac{1}{V}\right)$

Asbestos Content (as asbestos): $\% w/w = \frac{(m \times P_A)}{M}$

Weighted Average (of asbestos): $\%_{WA} = \sum \frac{(m \times P_A) \times x}{x}$

Terms

%asbestos	Estimated percentage of asbestos in a given matrix may be derived from knowledge or experience of the material, informed by HSG264 <i>Appendix 2</i> , else assumed to be 15% in accordance with WA DOH <i>Appendix 2 (PA)</i> . This estimate is not NATA-accredited.
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded (non-friable) condition. For the purposes of the NEPM and WA DOH, ACM corresponds to material larger than 7 mm x 7 mm.
AF	Asbestos Fines. Asbestos contamination within a soil sample, as defined by WA DOH. Includes loose fibre bundles and small pieces of friable and non-friable material such as asbestos cement fragments mixed with soil. Considered under the NEPM as equivalent to "non-bonded / friable".
AFM	Airborne Fibre Monitoring, e.g., by the MFM.
Amosite	Amosite Asbestos Detected. Amosite may also refer to Fibrous Grunerite or Brown Asbestos. Identified in accordance with AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004.
AS	Australian Standard.
Asbestos Content (as asbestos)	Total %w/w asbestos content in asbestos-containing finds in a soil sample (% w/w).
Chrysotile	Chrysotile Asbestos Detected. Chrysotile may also refer to Fibrous Serpentine or White Asbestos. Identified in accordance with AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004..
COC	Chain of Custody.
Crocidolite	Crocidolite Asbestos Detected. Crocidolite may also refer to Fibrous Riebeckite or Blue Asbestos. Identified in accordance with AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004..
Dry	Sample is dried by heating prior to analysis.
DS	Dispersion Staining. Technique required for unequivocal Identification of asbestos fibres by PLM.
FA	Fibrous Asbestos. Asbestos-containing material that is wholly or in part friable, including materials with higher asbestos content with a propensity to become friable with handling, and any material that was previously non-friable and in a severely degraded condition. For the purposes of the NEPM and WA DOH, FA generally corresponds to material larger than 7 mm x 7 mm, although FA may be more difficult to distinguish visibly and may be assessed as AF.
Fibre Count	Total of all fibres (whether asbestos or not) meeting the counting criteria set out in the NOHSC:3003
Fibre ID	Fibre Identification. Unequivocal identification of asbestos fibres according to AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004.. Includes Chrysotile, Amosite (Grunerite) or Crocidolite asbestos.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess the degree of friability.
HSG248	UK HSE HSG248, <i>Asbestos: The Analysts Guide</i> , 2 nd Edition (2021), ISBN: 9780616667079.
HSG264	UK HSE HSG264, <i>Asbestos: The Survey Guide</i> (2012), ISBN: 9780717665020
ISO (also ISO/IEC)	International Organization for Standardization / International Electrotechnical Commission.
K Factor	Microscope constant (K) as derived from the effective filter area of the given AFM membrane used for collecting the sample (A) and the projected eyepiece graticule area of the specific microscope used for the analysis (a).
LOR	Limit of Reporting.
MFM (also NOHSC:3003)	Membrane Filter Method. As described by the Australian Government National Occupational Health and Safety Commission, <i>Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres</i> , 2nd Edition [NOHSC:3003(2005)].
MMVF	Man-Made Vitreous Fibre - exhibiting isotropic characteristics, including glass fibres, glass wool, rock wool, slag wool, ceramic fibres and "bio-soluble fibres". NOTE: previously known as "synthetic mineral fibre" (SMF).
NEPM (also ASC NEPM)	National Environment Protection (Assessment of Site Contamination) Measure, (2013, as amended).
Organic	Organic Fibres Detected. Organic may refer to Natural or Man-Made Polymeric Fibres. Identified in accordance with AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004..
PCM	Phase Contrast Microscopy. This is used for fibre counting according to the MFM.
PLM	Polarised Light Microscopy. As used for Fibre Identification and Trace Analysis according to AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004..
Sampling	Unless otherwise stated, Eurofins are not responsible for sampling equipment or the sampling process.
SRA	Sample Receipt Advice.
Trace Analysis	An analytical procedure is used to detect the presence of respirable fibres (particularly asbestos) in a given sample matrix.
UK HSE HSG	United Kingdom, Health and Safety Executive, Health and Safety Guidance, publication.
UMF	Unidentified Mineral Fibre Detected. Fibrous minerals that are detected but have not been unequivocally identified by PLM with DS according to AS 5370:2024* Sampling and qualitative identification of asbestos in bulk materials (ISO 22262-1:2012, MOD), formerly AS 4964-2004.. It may include (but is not limited to) actinolite, anthophyllite, or tremolite asbestos.
WA DOH	Reference document for the NEPM. Government of Western Australia, <i>Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia</i> (updated 2021), including Appendix Four: <i>Laboratory analysis</i>
Weighted Average	Combined average %w/w asbestos content of all asbestos-containing finds in the given aliquot or total soil sample (% _{WA}).

Comments

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	No
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Asbestos Counter/Identifier:

Modhurika De Senior Analyst-Asbestos

Authorised by:

Zoe Burke Senior Analyst-Asbestos



Glenn Jackson
Managing Director

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.



Contact Information & Further Services

Thank you for engaging Greenlight. If you have any queries about the report or any other asbestos related matters, please do not hesitate to contact our office on:

Phone: 1300 888 001

email: info@greenlightservices.com.au

Please quote the report number: **1340.02.ARI Rev 0** when making contact so that we can view the site's report along with your enquiry.

Greenlight are an experienced occupational hygiene and project management company and may be of further assistance in the following areas:

- Online Asbestos Management Solutions for clients with more than one property to manage
- QR Code and NFC tag signage and labelling services (linked to an online asbestos register)
- Asbestos Removal Management – *Suitable only for larger projects*, we can:
 - Establish scope of works and obtain asbestos removal quotes,
 - Review the fitness of companies applying for works
 - Recommend a suitable removalist
 - Supervise works with air monitoring and clearance inspections
- Respirable Crystalline Silica Air Monitoring
- Mould Inspections and Air Quality Assessments
- Soil Testing for Off-Site Disposal (Waste Classification Reports)
- Asbestos Clearance Certificates;
- Asbestos Air Monitoring;
- Meth Testing & Clandestine Drug lab Investigations (for methamphetamine drug residue within the site); or
- Indoor Air Quality Assessments.

If you know anyone that may benefit from our services, **please put us in touch.**