

Nick Mob: 0432 199 016 Head Office Fax: 07 49514117

Email: <u>nick@ausnorthasbestos.com.au</u>

diane@ausnorthasbestos.com.au

Head Office: PO Box 3500, North Mackay 4740

## **WORK CLEARANCE CERTIFICATE**

Job Number	A00790		
Date	16.7.2018		
Area of Removal	Removal of 2 asbestos core fire doors from Building 361.		
Client Name	CQ University North Rockhampton		
Postal Address	Building 37, Level 1, Bruce Highway, North Rockhampton 470		
Site Address	Building 361, CQU Campus, North Rockhampton.		
Name of Supervisor/Licence Details.	Brendan Housman		
Licence Details	Class A Asbestos Removal: 2308445		

The area of removal has been visually inspected by a competent person independent of the removal. It has been visually assessed to ensure proper decontamination procedures have been used and that no evidence of asbestos containing material remains in the affected area.

The area is now deemed safe to reoccupy.

Name of inspector	Nick Trimble			
Signature	Delfu	00.		
Date of inspection	16.7.2018	Time of inspection	1.00pm	

## **Assessor Checklist**

To be used by the competent assessor in instances where a NATA approved hygienist is not monitoring the works.

		Yes	No
Do you have a copy of the asbestos ren	noval control plan/SWMS?	/	
Do you have a copy of the notification form?		/	
Is the removal work consistent with the	e control plan?	/	
	Visual Inspection		
Inspection of the specific removal area found no visual asbestos as a result of the removal work carried out. (Timbers have been de-nailed, no visual dust or debris.)			
Is the area safe to reoccupy?		/	
If no then the removal team must be in decontamination to an acceptable finis			
	2 <sup>nd</sup> Visual Inspection		
Inspection of the specific removal area the removal work carried out. (Timbers debris.)			
Is the area safe to reoccupy?			
Name of Inspector:		•	
Signature:			
Date of inspection	Time of Inspection		